

---

## TVM-N – Assembly Instruction

---

1. Unpack the test stand
2. Plug in the power supply



3. Attach a force gauge with an internal sensor



---

## TVM-N – Assembly Instruction

---

4. Attach a force gauge with an internal sensor
  - a. Dismount the red marked object



By unscrewing the four screws



---

## TVM-N – Assembly Instruction

---

- b. Connect the FH force gauge with the test stand (only FH U 5.1 series)



**5. Alternative, if an external sensor is to be mounted:**

- a. Take the black angle piece



---

## TVM-N – Assembly Instruction

---

- b. Attach the black angle piece to the upper part of the test stand



- c. Attach the external sensor

---

## TVM-N – Assembly Instruction

---

- d. Connect the sensor with the display unit (please see the operation manual)



Ready for measuring!